

**From:** Whelan, Joseph <JWhelan1@wm.com>  
**Sent:** Friday, April 1, 2011 1:48 PM  
**To:** 'Steven.chang@doh.hawaii.gov'; lene.ichinotsubo@doh.hawaii.gov; Miyashiro, Thomas <thomas.miyashiro@doh.hawaii.gov>; 'Tyahla.Stephen@epamail.epa.gov'  
**Subject:** FW: CQA Letter Report and Figure Showing Area Recommended for MSW Placement  
**Attach:** MSW Placement\_040111.pdf; Letter Report Cell E6 West Slope Repair\_4-1-11.pdf

---

Greetings all.

Please find the CQA report documenting the liner repairs related to the storm damage located within the northwest portion of Cell E6. We would appreciate your timely review and approval of this report. Currently we expect to have consumed available airspace by end of day today, Friday April 1<sup>st</sup>, and therefore request that approval to utilize the area described in this report today. We expect to provide you with the CQA report for the final portion of the repair to the northwest area on Monday April 4<sup>th</sup>. Thank you in advance for your assistance with this most important project.

Best regards,

Joe

---

**From:** Boyle, Ron [mailto:Ron.Boyle@aecom.com]  
**Sent:** Friday, April 01, 2011 12:14 PM  
**To:** Whelan, Joseph  
**Cc:** Frey, Jesse; Lottig, Justin; Frerich, Dan  
**Subject:** CQA Letter Report and Figure Showing Area Recommended for MSW Placement

Aloha Joe,

Please find attached our Liner Damage Assessment, Repair and CQA Report for recent repairs on the MSW Cell E6 Sideslope Liner. Also attached is a figure showing the recommended MSW filling area in Cell E6.

Please let me know if you have any questions.

Thank you.

**Ron Boyle, P.E.**  
Senior Engineer, Environment  
D 808.356.5321 Cell 808.497.5941  
[ron.boyle@aecom.com](mailto:ron.boyle@aecom.com)  
**AECOM Technical Services**  
1001 Bishop Street, Suite 1600  
Honolulu, HI 96813  
T 808.523.8874 F 808.523.8950  
[www.aecom.com](http://www.aecom.com)